TypeL #Hits	# Hit	Hit	10	Search Text	DBs	Time Stamp	StampComments	Error Definition	Errors
BRS L1 364 (aut	364	64	toil (aut flus	toilet near5 (automatic adj5 flush\$3)	USPAT; US-PGPUB; 2004/ EPO; JPO; 14:45 DERWENT	2004/10/25 14:45			0
BRS L2 385 (aut	385	8 5	toil (aut flus	toilet near8 (automatic adj5 flush\$3)	USPAT; US-PGPUB; 2004/ EPO; JPO; 14:45 DERWENT	2004/10/25 14:45			0
BRS L3 395 (autome flush\$3	395	95	toi (auf flus	near10 itic adj5 3)	USPAT; US-PGPUB; 2004/ EPO; JPO; 14:45 DERWENT	2004/10/25 14:45			0
ERS L4 443 (au1 flus	443	43	toi (auf flus	toilet same (automatic adj5 flush\$3)	USPAT; US-PGPUB; 2004/ EPO; JPO; 14:45 DERWENT	2004/10/25 14:45			0
BRS L5 156 L4 a	156 L4	56 L4		and sensor	USPAT; US-PGPUB; 2004/ EPO; JPO; 14:46 DERWENT	2004/10/25 14:46			0
BRS L6 16 board)	16		L5 ¿ boal	1 (circuit near2	USPAT; US-PGPUB; EPO; JPO; DERWENT	USPAT; US-PGPUB; 2004/10/25 EPO; JPO; 14:46 DERWENT	-		·
BRS L7 18 L4 and lever)	18		L4 1ev	(rotat\$4 near5	USPAT; US-PGPUB; 2004/ EPO; JPO; 14:48 DERWENT	2004/10/25 14:48		·	0